

Description

Henry® Pumadeq™ Catalyst is a reactive agent powder used to initiate curing of the Henry® Pumadeq System materials.

Application

For detailed mixing instructions, refer to Henry tech talk **Pumadeq Catalyst** mixing ratios.

Pumadeq Catalyst quantity required is based on an average of Pumadeq membrane, ambient and substrate temperatures.
 Be aware that temperature conditions vary in areas of project and at different times of day. Adjust catalyst accordingly.

- There are 20 volume oz. per 1lb weight of Catalyst.
- There are (80 volume oz.) of catalyst in a 5lbs/1 gallon pail (4lbs catalyst).
- There are (200 volume oz.) of catalyst in a 13lbs/3.5 gallons pail (10lbs catalyst).

Average Temperature	Pumadeq Catalyst Volume: oz added per 1 gallon of Pumadeq Membrane		Pot Life (minutes)
	Henry® Pumadeq Primer 20 Henry® Pumadeq Flex 30SL, 31MV, 32TX Henry® Pumadeq Grip (ounces)	Henry® Deqcoat 50 (Including more catalyst than recommended can cause yellowing)	
20 °F -40 °F (-7 °F – 4 °C)	Contact Henry® Product Support	Contact Henry® Product Support	
40 °F (4 °C)	10	7	15
50 °F (10 °C)	8	5	15
60 °F (16 °C)	6	4	10-15
70 °F (21 °C)	4	3	10-15
80 °F (27 °C)	3	2.5	10
90 °F (32 °C)	2	2	10

Product mixing: Only catalyze the amount of material that can be applied within the estimated pot life (10-15 minutes). It is recommended to start by catalyzing 1 gallon of any **Pumadeq** membrane to determine pot life.

Pumadeq membrane and **Pumadeq Catalyst** must be thoroughly mixed, using an electric, slow speed (300-400rpm), high torque drill with CLEAN, spiral, mixing paddle (Jiffy type, size according to material amount mixed), to achieve a uniform distribution of the catalyst and paraffin contained in the product.

- 1) Pre-mix **Pumadeq** membrane for a minimum of 1 minute, longer at colder temperatures
- 2) Then mix **Pumadeq** membrane together with **Pumadeq Catalyst**, for 1 minute minimum
 A one oz. (volume) scoop is provided with each pail of catalyst

NOTE: Before using **Pumadeq Catalyst**, please refer to Safety Data Sheet (SDS). Ensure the same safe working methods are followed for all persons in the work area. Wear suitable protective clothing, butyl rubber or nitrile gloves and safety goggles with side shields during mixing and application.

When **Pumadeq Catalyst** is applied in enclosed areas without natural ventilation, forced ventilation must be arranged. Avoid strong concentration of vapor as well as direct contact with skin or eyes. If concentration exceeds recommended limits in SDS, a NIOSH approved respirator (OSHA 29 CFR 1910.134) is required. **Pumadeq Catalyst** has a low flashpoint; keep away from all sources of ignition and do not smoke. Uncured polymers, resins and catalyst powder may be toxic. They may cause allergic reactions or hypersensitivity reaction.

- Contact with skin – wash immediately with soap and water.
- Contact with eyes – rinse immediately with lots of water and seek medical attention

Pumadeq™ Catalyst

Packaging

5lbs (1 gallon) pail contains 4lbs of catalyst
12lbs (3.5 gallons) pail contains 10 lbs of catalyst

Shelf Life/ Storage

One year with proper storage. Always store **Pumadeq Catalyst** in a cool and dry location. Do not store in direct sunlight or in temperatures above 80° F (27 °C).

For more information, visit www.henry.com or for technical assistance call us at 800-486-1278. For more information on Henry's® product warranty and liability disclaimer please visit www.henry.com/warranty. Refer to the Safety Data Sheet prior to using this product. The Safety Data Sheet is available at www.henry.com or by emailing Henry® Product Support at productsupport@henry.com or by calling 800-486-1278.

Henry is a registered trademark of the Henry Company

The technical and application information herein is based on the present state of our best scientific and practical knowledge. As the information herein is of a general nature, no assumption can be made as to a product's suitability for a particular use or application and no warranty as to its accuracy, reliability or completeness either expressed or implied is given other than those required by law. The user is responsible for checking the suitability of products for their intended use. Henry® Company data sheets are updated on a regular basis; it is the user's responsibility to obtain and to confirm the most recent version. Information contained in this data sheet may change without notice.